

ENERGETIKA RAVNE, d.o.o.

gryod GABERŠEK!

5. VII. 00

Jamšek

Ravne, July 4th 2000

RP 12.00/1029/RJ

**SUBJECT: INSPECTION OF TUBE HEAT EXCHANGER (2X) UHP FURNACE,
OPEN SYSTEM 40/30 °C**

Upon the agreement with Mr Petovar, we have concluded to inspect both tube heat exchangers on the secondary part of the UHP furnace on Tuesday, July 4th 2000. The front and rear covers of both exchangers shall be disassembled.

PRESENT AT INSPECTION:

Petovar – SŽ Metal Ravne, d.o.o. JUH OTO

Oderlap, Vučko, Potočnik, Jamšek, Zapušek – Energetika Ravne, d.o.o.

ESTABLISHMENTS:

The inspected tubes were clean; there were no signs of lime scale accumulation.

The device for electronic softening is functioning well.

CONCLUSION:

We suggest that the device is purchased.

Petovar


Oderlap
Jamšek
Zapušek

ENERGETIKA RAVNE d.o.o.
RAVNE NA KOROŠKEM
①

PRESENTATION OF ASSEMBLY AT SŽ-METAL d.o.o. RAVNE



SITUATION BEFORE INSTALLATION – ADJUSTMENT OF TUBE Ø



SITUATION AFTER INSTALLATION
AND SWITCH-ON



CONTROL OF HONEY COMB
FILL OF COOLING TOWER