

## Vulcan installed in a Chiller

Dear CWT Team,

Here are two pictures from a Chiller opened for a routine cleaning, but nothing to clean after two years with Vulcan treatment.



No scale formation after using Vulcan



This Chiller is connected to a Cooling Tower which is exposed to lots of air borne contamination from surrounding farms.

Best Regards

Arne Vestad  
[www.IWTNA.com](http://www.IWTNA.com)